



Oracid™ Plus

Non-Foam C.I.P. Acid Rinse

Oracid Plus is a highly concentrated, non-foaming C.I.P. acid rinse.

Features and Benefits

- Powerful, Commercial-Grade Cleaner**
 This highly concentrated acid has all the cleaning power needed to work in large or hard-to-clean systems.
- Non-Foaming**
 Designed specifically for C.I.P. acid rinsing. Rinses completely and quickly.
- Phosphoric Acid Base**
 Completely neutralizes detergent residues to prolong the life of liners and other rubber parts.
- Contains Nitric Acid**
 Not only removes complex organic and inorganic scales, but has been shown to protect steel.
- No Sulfuric Acid**
 Can be used with water that contains barium.
- Safe**
 Safe to use. Non-corrosive to stainless steel, glass or rubber parts when properly mixed at recommended dilution rate.
- Biodegradable**
 Dissipates freely and will not harm sanitary systems.
- 100% Customer Satisfaction**
 All GEA Farm Technologies hygiene products have a 100% Customer Satisfaction Guarantee.



GEA Farm Services | WestfaliaSurge



Oracid™ Plus

Non-Foam C.I.P. Acid Rinse

Directions for Use

For acid rinsing pipelines and milk tanks.

1. Rinse pipeline with clean, warm 95°-110°F (35°-43°C) water immediately after use or as soon as tank is emptied.
2. Mix a GEA Farm Technologies pipeline or milk tank cleaner at recommended concentration. Circulate for 10 minutes or until temperature drops below 120°F (49°C).
3. Rinse with warm or cold water using 1 oz. (30 ml) Oracid Plus to each 5 gallons (18.9 L) of water. If water hardness and alkaline residue is minimal, a 1 oz. (30 ml) to 10 gallon (38 L) dilution can be used.
4. Sanitize prior to milking with a GEA Farm Technologies sanitizer according to local health department regulations.

NOTE: The type and amount of acid required for proper cleaning and rinsing is related to water quality and buffers, detergent type, system design and other chemical and physical factors. Consult your GEA Farm Technologies hygiene specialist for specific recommendations to ensure proper use and performance of Oracid Plus.

Product Properties

Appearance:	Clear orange/red liquid
Odor:	Mild acid
pH:	<2.0
Specific Gravity at 77°F (25°C):	1.17 (water = 1)
Foam:	Non-foaming
Solubility:	Complete at recommended use dilutions

Ordering Information

U.S. & Canada	
SKU	Description
7751-0042-516	Oracid Plus - 5 gal. pail (18.9 liters)
7751-0042-349	Oracid Plus - 15 gal. drum (56.7 liters)
7751-0042-356	Oracid Plus - 30 gal. drum (113.5 liters)
7751-0041-058	Oracid Plus - 55 gal. drum (208 liters)
7751-1000-484	Oracid Plus - Literature (pkg of 20)

GEA Farm Technologies

GEA Farm Technologies, Inc.

1880 Country Farm Drive, Naperville, IL 60563
Toll Free: 1.877.WS.DAIRY or 1.877.973.2479
www.gea.com | www.gea-farmtechnologies.com

GEA Farm Technologies Canada, Inc.

4591 boulevard St-Joseph, Drummondville, QC J2A 0C6
Toll Free: 1.877.WS.DAIRY or 1.877.973.2479
www.gea.com | www.gea-farmtechnologies.com

7751-1000-484 (pkg of 20)
(rev. 07-13)